# MODEL BGC 2 SPEED CLIPPER 120 VOLT




| ITEM NO. | PART NO. | DESCRIPTION | QTY. REQ'D |
|---|---|---|---|
| 1 | 65267 | Drive Cap - Black | 1 |
| 2 | 22962 | Upper Housing Assy - Black | 1 |
| 3 | 21063 | Insulator | 1 |
| 4 | 27198 | Motor Frame Clip | 1 |
| 5 | 65828 | Screw | 2 |
| 6 | 22681 | Switch and Circuit Board Assembly | 1 |
| 7 | 27352 | Field Assembly | 1 |
| 8 | 65805 | Brush Retaining Clip | 1 |
| 9 | 64965 | Insulator | 1 |
| 10 | | Hanger Bail | |
| 10a | 22267 | (for units after 7/3/03) | 1 |
| 10b | 25061 | (for units before 7/3/03) | 1 |
| 11 | 63327 | Rear Motor Frame | 1 |
| 12 | | Lower Housing | |
| 12a | 22852 | Lower Housing (BGC2 UL) - Black | 1 |
| 12b | 22854 | Lower Housing (BGC2 CSA) - Black | 1 |
| 13 | 64606 | Front Housing Screw | 2 |
| 14 | | Hinge Assembly | |
| 14a | 28194 | Hinge Assy (BGC & Oster 76 & 89) | 1 |
| 14b | S27091 | Hinge Assy (BGC & Oster 10,22,111) | 1 |
| 15 | 27864 | Blade Hinge Screw | 2 |
| 16 | 27847 | Carbon Brush With Shunt | 2 |
| 17 | 64003 | Blade Bracket | 1 |
| 18 | 64139 | Blade Screw | 2 |
| 19 | 64027 | Blade Guide | 1 |

| ITEM NO. | PART NO. | DESCRIPTION | QTY. REQ'D |
|---|---|---|---|
| 20 | 64013 | Tension Spring | 1 |
| 21 | 21977 | Armature Assembly (Includes #22) | 1 |
| 22 | 27854 | Cam and Bearing Assembly | 1 |
| 23 | 21068 | Large Bearing Cup | 1 |
| 24 | 65581 | Front Motor Frame | 1 |
| 25 | S20651 | Blade Drive Assembly | 1 |
| 26 | 15766 | Blade Drive Screw | 2 |
| 27 | 22086 | Rear Housing Screw | 2 |
| 28 | 26049 | Cord Set | 1 |
| 29 | 21067 | Small Bearing Cup | 1 |
| 30 | 65806 | Brush Spring | 1 |
| 31 | 64991 | Oil Seal | 1 |
| 32 | 17091 | Self-Adhesive Foam Pad | 1 |
| 33 | 22909 | Blade Retaining Spring | 1 |

**IMPORTANT INFORMATION**

**When ordering repair parts, include part number, part name and model of trimmer. For best performance, trimmer blades should be CLEANED and OILED with Andis Clipper Oil before and after use, If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin, 53177 U.S.A.. Pack carefully, mail either Insured Parcel Post, or U.P.S. , attach a letter to outside of package explaining difficulty.**