



ITEM NO.	PART NO.	DESCRIPTION	QTY. REQ'D
1		Drive Cap	
1a	65267	Drive Cap - Black	1
1b	65266	Drive Cap - Red	1
1c	22449	Drive Cap - Blue	1
1d	22448	Drive Cap - Silver	1
2		Upper Housing	
2a	22964	Upper Housing - Black	1
2b	22959	Upper Housing - Red	1
2c	22466	Upper Housing - Blue	1
2d	22467	Upper Housing - Silver	1
3	21063	Switch Insulator	1
4	27198	Motor Frame Clip	1
5	65828	Screw	1
6	22681	Circuit Board	1
7		Field Assembly	
7a	22453	Field Assy. (Super 2)	1
7b	27352	Field Assy. (AGC2)	1
8	65805	Brush Retaining Clip	2
9	22267	Hanger Bail	
10	64945	Rear Motor Frame	1
11		Lower Housing	
11a	65559	Lower Housing - Black	1
11b	65263	Lower Housing - Red	1
11c	65557	Lower Housing - Blue	1
11d	65383	Lower Housing -Silver	1

ITEM NO.	PART NO.	DESCRIPTION	QTY. REQ'D
12	64606	Front Housing Screw	2
13	S63897	Hinge Assembly	1
14	64537	Blade Lock	1
15	64535	Lock Keeper	1
16	27864	Blade Hinge Screw	2
17	27847	Carbon Brush	2
18	64003	Blade Bracket	1
19	64139	Blade Screw	2
20	64027	Blade Guide	1
21	64013	Tension Spring	1
22	27072	Armature Assy. (includes #24a)	1
23	27251	Metal Cam and Bearing Assembly	1
24	21068	Large Bearing Cup	1
25	65581	Front Motor Frame	1
26	S20651	Blade Drive Assembly	1
27	15766	Blade Drive Screw	2
28	22086	Rear Housing Screw	2
29	64250	Cord Set	1
30	21067	Small Bearing Cup	1
31	65806	Brush Spring	2
32	64991	Oil Seal	1
33	17091	Self Adhesive Foam Pad	1

IMPORTANT INFORMATION

When ordering repair parts, include part number, part name and model of trimmer. For best performance, trimmer blades should be CLEANED and OILED with Andis Clipper Oil before and after use. If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin, 53177 U.S.A.. Pack carefully, mail either Insured Parcel Post, or U.P.S. , attach a letter to outside of package explaining difficulty.