



POS	PART NO	DESCRIPTION	TOTAL
1	<a href="#">706-501</a>	Clinner head case	1x
2	<a href="#">706-503</a>	Cutter driving carrier	1x
3	<a href="#">706-505</a>	Crank spindle sleeve	1x
4	<a href="#">706-506</a>	Crank spindle	1x
5	<a href="#">706-507</a>	Crank driveblock	1x
6	<a href="#">701-710</a>	Gearwheel 52teeth	1x
7	<a href="#">706-509</a>	Tension screw	1x
8	<a href="#">706-510</a>	Distance screw	1x
9	<a href="#">706-511</a>	Pressure plate	1x
10	<a href="#">706-514</a>	Centering ring	2x
11	<a href="#">706-517</a>	Pressure spring	1x
12	<a href="#">706-518</a>	Laminated springs complete	2x
13	<a href="#">706-520</a>	PHscrew MS x 16	2x
14	<a href="#">706-521</a>	Blade screw MS x 14	2x
15	<a href="#">701-713</a>	PT screw flat, KA 40 X 14	2x
16	<a href="#">706-524</a>	Circlip Benzing for gear wheel 06 DIN6799	1x
17	<a href="#">706-525</a>	Cylindric screw with shank M3 x 6	2x